



**Application
Parameters**

Pipe

Output Signal / Measuring Range Pressure:

DC 0...10 V / 0...1 bar	22WDP-111	4...20 mA / 0...1 bar	22WDP-131
DC 0...10 V / 0...2.5 bar	22WDP-112	4...20 mA / 0...2.5 bar	22WDP-132
DC 0...10 V / 0...4 bar	22WDP-114	4...20 mA / 0...4 bar	22WDP-134
DC 0...10 V / 0...6 bar	22WDP-115	4...20 mA / 0...6 bar	22WDP-135
DC 0...10 V / 0...4 bar	22WP-114	4...20 mA / 0...4 bar	22WP-134
DC 0...10 V / 0...6 bar	22WP-115	4...20 mA / 0...6 bar	22WP-135
DC 0...10 V / 0...10 bar	22WP-116	4...20 mA / 0...10 bar	22WP-136
DC 0...10 V / 0...16 bar	22WP-117	4...20 mA / 0...16 bar	22WP-137